



OFFICIAL INSPECTION REPORT

Facility FA0211895 - SANTA CLARA INT'L SWIM CENTER-LAP		Site Address 2625 PATRICIA DR, SANTA CLARA, CA 95050		Inspection Date 02/28/2024	
Program PR0310345 - REC BODY OF WATER 5,000 SQ FT & OVER RC 3 - RH04			Owner Name CITY OF SANTA CLARA		Inspection Time 11:10 - 12:00
Inspected By FARHAD AMIR-EBRAHIMI	Inspection Type ROUTINE INSPECTION	Consent By ALEX AUERBACK			

Placard Color & Score
N/A
N/A

Mail To: SANTA CLARA INT'L SWIM CENTER
 PARKS SERVICE CENTER
 2600 BENTON ST
 SANTA CLARA, CA 95051

Pool Violations:

R02 - Approved ENCLOSURE properly installed and maintained in good repair

OU

Fencing and enclosure.

A. Gaps located in chain link fence.

1. Gaps range in size between 5 inches and 2.5 – 3 inches.
2. Areas of fencing seen to be under landscaping rather than concrete.
3. Climbable vegetation observed along some fence areas.
4. Areas between post and gate may allow passage of a 4-inch sphere.
5. South fencing has a trash can located outside enclosure which may be used for climbing into pool area.
6. Some fencing has a gab between the fence and concrete which may allow the passage of a 4-inch sphere.
7. West area enclosure has a 41-inch climbable post.
8. North area enclosure has a gate latch which is 41 inches and may allow climbing.

[CA] The pool shall be enclosed by one or a combination of the following: a fence, portion of a building, wall, or other approved durable enclosure. Doors, openable windows, gates of living units or associated private premises shall not be permitted as part of the pool enclosure. The enclosure, doors and gates shall meet all of the following specifications:

1. The enclosure shall have a minimum effective perpendicular height of 5 feet (1524 mm) as measured from the outside as depicted in Figure 31B-4; and
2. Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a 4-inch (102 mm) diameter sphere. The enclosure shall be constructed over a hard and permanent material equivalent to concrete; and
3. The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Horizontal and diagonal member designs which might serve as a ladder for small children are prohibited. Horizontal members shall be spaced at least 48 inches (1219 mm) apart. No planters or other structures that can be climbed shall be permitted within 5 feet (1524 mm) of the outside of the pool enclosure or within a 5 foot (1524 mm) arc as depicted in Figure 31B-5. The area 5 feet (1524 mm) outside of the pool enclosure shall be a common area open to the public; and
4. Chain link may be used, provided that the openings are not greater than 1¼ inches (44 mm) measured horizontally.

R05 - Proper size and accessibility of LIFE RING with proper length of ATTACHED ROPE provided

OU

Life ring and rescue pole are available only on one side of the pool [CA] For public pools that exceed 75 feet in length or 50 feet in width, the pool operator shall provide a rescue pole and a life ring on at least two opposing sides of the public pool at centralized locations.

R12 - POOL SHELL, BOTTOM & SIDES maintained in a safe and sanitary condition

OU

Plaster is damaged various areas and brown discoloration in the pool [CA] Repair or replaster the pool

Some side tiles have fallen inside the pool [CA] Remove fallen tiles and reinstall missing tiles

R13 - PERMANENT MARKINGS properly installed and maintained in good repair

OU

"No Diving" markers required adjacent to depth marking tiles [CA] Provide "No Diving" markers adjacent to depth marking tiles.

OFFICIAL INSPECTION REPORT

Facility FA0211895 - SANTA CLARA INT'L SWIM CENTER-LAP	Site Address 2625 PATRICIA DR, SANTA CLARA, CA 95050	Inspection Date 02/28/2024
Program PR0310345 - REC BODY OF WATER 5,000 SQ FT & OVER RC 3 - RH04	Owner Name CITY OF SANTA CLARA	Inspection Time 11:10 - 12:00

R21 - HANDHOLDS & POOL DECK maintained in a safe and sanitary condition OU
On the West side ladder is lose [CA] Make the ladder secure

R31 - Functional FLOWMETER provided OU
REPEAT VIOLATION:

Flowmeter not functioning on recirculation system [CA] Repair or replace flow meters on recirculation system to accurately measure flow rate within 10% of flow

SR15 - All gates and doors are capable of being locked during times when the pool is closed OU
Gates are not self-closing and self-latching [CA] Gates and doors opening into the pool enclosure also shall meet the following specifications:

- 1. Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. Hand activated door or gate opening hardware shall be located at a height no lower than 42 inches (1067 mm) but no higher than 44 inches (1179 mm) above the deck or walkway; and**
- 2. Gates and doors shall be capable of being locked during times when the pool is closed. Exit doors which comply with Chapter 10, Title 24, California Code of Regulations shall be considered as meeting these requirements; and**
- 3. The pool enclosure shall have at least one means of egress without a key for emergency purposes. Unless all gates or doors are so equipped, those gates and/or doors which will allow egress without a key shall have a sign in letters at least 4 inches (102 mm) high stating EMERGENCY EXIT; and**
- 4. The enclosure shall be constructed so that all persons will be required to pass through common pool enclosure gates or doors in order to gain access to the pool area. All gates and doors exiting the pool area shall open into a public area or a walkway accessible by all patrons of the pool.**

SR19 - Deck width is at least 4 feet around pool as measured from coping lip OU
1. Hose runner on deck. This is a tripping hazard [CA] Remove hose runner on deck to reduce risk of trip hazard.

2. Concrete cracked near west side ladder [CA] Repair/replace/service concrete near ladder.

SVRS Observation:

No significant health code violations observed at time of inspection.

Measured Observations

<u>Item</u>	<u>Location</u>	<u>Measurement & Comments</u>
Cyanuric acid		0.00 PPM
pH		7.60 pH
Chlorine		2.00 PPM

Overall Comments:

I conducted a joint inspection with Senior Environmental Health Specialist Aziz Husein. We met with Alex Auerbach, Parks Foreperson, with City of Santa Clara, and other City officials, including Cynthia Bojorquez, Assistant City Manager. According to Alex Auerbach this pool has been self-closed since January 2024.

You are hereby directed to correct all violations regarding the pool enclosure and gates due to safety concerns. Submit plans to this Department by 03/22/24 for approval prior to any modifications to the pool enclosure and gates.

For any structural modification, such as replastering the pool, plans must be submitted for approval to Plan Check section of this Department.

Pool must remain closed until all safety concerns are addressed. Contact the Department of Environmental Health for inspection prior to reopening the pool.

OFFICIAL INSPECTION REPORT

Facility FA0211895 - SANTA CLARA INT'L SWIM CENTER-LAP	Site Address 2625 PATRICIA DR, SANTA CLARA, CA 95050	Inspection Date 02/28/2024
Program PR0310345 - REC BODY OF WATER 5,000 SQ FT & OVER RC 3 - RH04	Owner Name CITY OF SANTA CLARA	Inspection Time 11:10 - 12:00

CLOSURE / PERMIT SUSPENSION NOTICE

When required to determine compliance, a single reinspection will be conducted without additional charge. If subsequent reinspections are required, an hourly fee (minimum one hour) at the current rate approved by the Board of Supervisors will be assessed for each and every reinspection until the necessary changes or corrections are made. Unless otherwise noted by the inspector, all violations are to be corrected no later than **3/13/2024**. Any major change in menu or any change in ownership must have prior approval by this Department. This may require structural and/or equipment changes or remodeling to accommodate new operations.

This notice is to inform you that as of this date the Environmental Health Permit for the above mentioned pool facility is hereby suspended and all operations therewith are ordered to cease. This action is taken in accordance with Section 65545 of the California Code of Regulations which states "A public pool that is maintained or operated in a manner that creates an unhealthful, unsafe, or unsanitary condition may be closed by the enforcing agent. A public pool shall not be reopened until the unhealthful, unsafe, or unsanitary condition has been rectified and upon specific written approval from the enforcing agent."

You have the right to make a written request for a hearing within 15 days after receipt of this notice to show just cause why the permit suspension is not warranted. Failure to request such a hearing within the 15-day period shall be deemed a waiver of the right to a hearing. After these violations have been corrected, you must call the Department of Environmental Health for a reinspection to reinstate the permit to operate. Phone #: (408)918-3400.

Legend:

[COS]	Corrected on Site
[CA]	Corrective Action
[PPM]	Part per Million
[SA]	Suitable Alternative
[SVRS]	Safety Vacuum Release System

	Account ID: AR1211895	Permit Exp. Date:
	Payment can be made online by visiting www.EHinfo.org .	